



## iiAssessment - Guardrails

---

### CLIENT INFORMATION:

Client: \_\_\_\_\_  
Project Name: 6-21-2013 \_\_\_\_\_  
Project #: \_\_\_\_\_  
Date: 6/27/2013 \_\_\_\_\_  
Project Manager: \_\_\_\_\_  
Field Inspector: \_\_\_\_\_

### LOCATION INFORMATION:

Asset ID: 154 \_\_\_\_\_  
Address: IR 71, MP 147.3103, Morrow County \_\_\_\_\_  
Longitude: -82.77158 \_\_\_\_\_  
Latitude: 40.46087 \_\_\_\_\_  
Direction: S \_\_\_\_\_

---

### FIELD DATA:

Length: 56 \_\_\_\_\_  
Width: N/A \_\_\_\_\_  
Height: N/A \_\_\_\_\_  
Type: N/A \_\_\_\_\_  
Material: Steel \_\_\_\_\_  
Concrete deficiencies: 0 (Acceptable) \_\_\_\_\_  
Post deficiencies: 0 (Acceptable) \_\_\_\_\_  
Spacer block deficiencies: 1 (Unacceptable) \_\_\_\_\_  
Rail deficiencies: 0 (Acceptable) \_\_\_\_\_

### COMMENTS:

