

- Accurately measure complex shapes with easy to use “Shape Tools”.
- Instantly capture, record, and store several part tolerances at one time.
- Thickness, Step Height, Width, Angle, Radius, Location, Gap and Depth.

