

**Infection Preventionists**

**When was your last hospital wide mattress inspection?**

**How many were discarded and replaced due to failure level contamination?**

Failed Mattress

Interior



**WE HAVE A FASTER, EASIER, MORE ECONOMICAL AND MORE COMPLIANT  
ALTERNATIVE MATTRESS MAINTENANCE PROGRAM FOR YOU**

ECRI recently issued a guidance document on mitigating the risks of bed and stretcher support surface fluid ingress and microbiological contamination. Among its numerous recommendations were inspecting mattress covers and interiors during room turnover, adding mattresses to the inspection and preventive maintenance schedule, and adding launderable mattress barrier covers to protect patients.

**Imagine**

- **An alternative mattress maintenance program proven to reduce C-diff infections by as much as 50% and that exceeds JC maintenance, inspection and testing requirements.**
- **Ability to tell every patient, every time, that they are protected when admitted to your facility.**
- **Reducing your mattress failure rate and spending less on mattress/mattress cover replacement every year.**
- **Saving your EVS team time with an easy to implement, compliant bed turnover process.**

**TRINITY GUARDION® Protective Patient Barrier**-CDC compliant high-heat launderable microbarrier system with a unique identifier barcode for complete inspection documentation. Inspection is performed after each patient discharge, during the laundering process. The microbarrier prevents ingress and egress of bodily fluids, microbes and contaminated particles, protecting patients and mattresses, while prolonging mattress life.