



Novapure

Novapure Systems Inc.

Suite 201, 1204 Kensington Rd. NW

Calgary, Alberta T2N 3P5

Email info@novapure.com

Example of an exterior wall – left side treated with Solarclean Photocatalytic Coating (applied August 1999)



The treated left side of this exterior wall has retained its original clean appearance. The untreated right side of the wall is discolored with grime. The photocatalyst was applied August, 1999 and the photograph was taken September, 2004. The treated left side will continue to remain clean because contaminants are continuously oxidized on the surface by the light-activated photocatalyst. Dirt and oils are washed off with each rainstorm.